
1. The method of packaging and dimension are shown as below figure. (Dimension in mm)



3. Label

- 3.1 The information of inner box label must be listed: (Description of a sample label)
 - TYPE 3.1.1 3.1.2 3.1.3 3.1.4 3.1.5 3.1.6 P/C 3.1.7

means (Product) TYPE (Part No.) means (Order No.) (P/O No.) means (Customer No.) (Part No.) means (Product) Quantity (QTY) means Dice Lot No./ Code (D/C) means Production Code (P/C) means Manufacturing Date (RMK)

3.2 The information of carton label must be listed;

3.2.1 TYPE 3.2.2 QTY

